

Head Styles



"H" Tip-Serrated used to test long leads, terminals, wire wrap posts and pads.



"K" Tip-Star used to penetrate through holes, pads and gold edge fingers. Will not be contaminated by dust.



"M3" Tip-seven-Needle used to test lands, pads. Spear point penetrates thin layers of oxides or contaminations.



"M7" Tip-seven-Needle used to test lands, pads. Spear point penetrates thin layers of oxides or contaminations.



"Q" Tip-Tulip used to test lands, terminals, and wire wrap posts.




"Q" Tip-Tulip used to test lands, terminals, and wire wrap posts.



"T" Tip-Chiseled Spear Point used to test through holes, pads and gold edge fingers.



"T" Tip-Chiseled Spear Point used to test through holes, pads and gold edge fingers.



"S" Tip-4 side Chisel used to test through holes, pads and gold edge fingers.



"S" Tip-4 side Chisel used to test through holes, pads and gold edge fingers.